

Annexure D

BUILDING SAFETY CERTIFICATE

No. 06

Dated: 23.04.2024

It is certified that the existing building Smriti Public School (name of the building or premises) at Bojhwa, Bhira, Palia Lakhimpur- Kheri (UP) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 02	NA	NA	NA	NA	NA

The building is owned/occupied by Smriti Public School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rural Engineering Department (Name of Department/ Govt.) on 19.04.2024 (date of inspection) in the presence of Mr. Amit, Bhira, Palia Lakhimpur- Kheri (UP) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 19.04.2024 for a period of 05 (five) years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1- If intensity of earthquake, in this region, occurs more than 06.00 on Richter scale this certificate become invalid. Inspection of building should be done again.
- 2- If no. of floor is increased then this certificate become invalid.

3

4

Issued on 19.04.2024 at Lakhimpur, Kheri

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

सहायक अभियंता

पी० आई० यू० ग्रा०

लखीमपुर-खैर

Name : Santosh Kumar

Designation : Assistant Engineer

Name & Address of Department/ Office: Rural Engineering Department Lakhimpur